

HOT TANK OVERHEAT (ROR PROTOCOL TRIGGERED)

The **WL3 FX Water Treatment System** has an ROR (Rate of Rise) protocol in the programming that will disable the hot tank and give audible and visual alarms if the temperature in the Hot Tank rises too rapidly, which usually indicates dry heating. The Hot Tank **MUST HAVE WATER IN IT** before the Green heater/compressor switch is turned on. Heating without water can damage the tank and the machine.

If this occurs, disconnect the machine from power for 10 seconds to allow the alarm to reset. Turn OFF the Green switch. Reconnect to power, with the Red Power switch ON and the Green switch OFF. Dispense water from the hot tank as normal. Once water flows, turn the Green switch back ON. If there is no water flowing from the hot tank, investigate further for other potential failures.

