


PRODUCT SUPPORT TECHNICAL BULLETIN

November 2nd, 2023

Topic: WL900 SS Auger Motor Coupler

History:

Past versions of the Auger Motor Coupler (22-1290) were made of high strength resins but were problematic. The newest version of the Auger Motor Coupler (22-1290SS) has been made of Stainless Steel and has also combined the Coupler with the Coupler Connector. Less parts to fail or lose. The new Coupler displays superior strength, consolidates parts, and does not have any negative effects on the operation of the unit. Shown below are past versions of the Coupler and the now-obsolete Coupler Connector, as well as photos of the new Coupler.



22-1290 (obsolete)

22-1290SS



22-1265 (obsolete)

Solution:

It is our recommendation that any WL900 in the field have the 22-1290 and 22-1265 uninstalled and the 22-1290SS installed in their place.

If you have a WL900 that needs a 22-1290SS, please create a warranty claim through the Dealer Resource Center.