## PRODUCT SUPPORT TECHNICAL BULLETIN

August 3, 2023

## Issue: S4, Base Mounting Holes

## **Purpose:**

Some base stands for the S4 do not have the mounting holes required to secure the unit to the base. This document will outline the solution and provide a template for identifying the location for holes to be manually drilled, allowing the S4 to be mounted to the base.

## **Solution:**

Mark holes to be drilled using the template below. Use a 3/8" bit to drill the holes. All measurements are marked from the outer edge of top frame. Figure 3 is the finished product.

**Process: Approx 15-minute fix.** 

